

U.S. Department
of Transportation
**Federal Highway
Administration**

**LTPP Seasonal Monitoring
Program**
Site Monitoring Suspension
Status Report
Section 331001, Concord
New Hampshire

SMP SITE MONITORING SUSPENSION STATUS REPORT NEW HAMPSHIRE SECTION 331001

I. INTRODUCTION

The seasonal site 331001 near Concord, New Hampshire was installed on October 13 - October 14, 1993. Seasonal data was collected continuously from October 14, 1993 to June 29, 1995. On June 29, 1995, all site suspension activities were completed at this site according to LTPP directive SM-8 "Suspension of SMP Site Monitoring Activities". The site will remain out of operation until the next round of testing which is tentatively scheduled for September 1996.

This report entitled "SMP Site Monitoring Suspension Status Report" details the suspension preparation activities, site specific conditions, and provides information pertinent to the seasonal site 331001.

II. SUSPENSION PREPARATION ACTIVITIES

The suspension preparation activities at 331001 were conducted during the final two site visits. A manual distress survey of the entire section and transverse Dipstick[®] surveys were conducted on the June 01, 1995 site visit. PK nails were reconfirmed and replaced as required. The site paint markings were refreshed at this time. June 29, 1995 was the last day of activity at the site. On this day three sets of FWD tests, one set of elevations, and a distress survey of the instrumentation area were conducted. The water table measurements and the manual resistivity measurements (2 and 4 point) were performed in the morning and once after noon. The onsite datalogger was downloaded before being dismantled. Two sets of TDR traces and resistance voltages were extracted by the mobile datalogger. The instrument hole, trench, and surface temperature probe slot areas were cleaned and sealed as needed.

The air temperature probe, tipping bucket, and the upper part of the support pole were dismantled. The lead wires from the air temperature probe and the tipping bucket were sprayed with an anti-corrosive compound and sealed in an air tight bag with desiccant packs. A galvanized wire fished through the pipe and conduit will be used to pull the instrumentation wires back on the re-initiation of data collection at the site. The bottom part of the support pole was cleaned and lubricated prior to installing the end cap.

After all the wires were disconnected from the control panel, the panel was detached from the equipment cabinet with the CR10 datalogger, terminal strip, and the battery pack attached to it. The TDR cables were checked to ensure that they were labeled. The TDR cables, resistivity cable, and the MRC lead wires were sprayed with anti-corrosion

compounds and sealed in air tight bags with desiccant packs. All cables were hung up high inside the equipment cabinet. After the last piezometer reading was recorded the pipe was cleaned and sealed with grease. The access cover and seat were cleaned and lubricated before being covered and brought up to grade with the native soil.

The Profilometer survey corresponding to the closeout was conducted on May 18, 1995.

All the necessary suspension activities were completed by June 29, 1995. The dismantled equipment was removed from the site. The suspended site contains all the under ground instrumentation and equipment, and an equipment cabinet with all the cables in it. The equipment cabinet was locked before leaving the site. The site was cleaned and left in a condition such that the instrumentation could be easily accessed when and if site monitoring activities should resume.


III. SPECIAL SITE CONDITIONS

The installation of site 331001 followed the "LTPP Seasonal Monitoring Program: Instrumentation Installation and Data Collection Guidelines" closely. There were no irregularities associated with the installation of this site.

IV. SUPPLEMENTAL INFORMATION

Figure 1 shows the locations of the installed instrumentation at the site. The instrumentation hole is at station 0-16 and the piezometer is at station 1+00. Figure 2 gives the plan view of the portion of test section 331001 that was used for elevation measurements. All offsets are measured from the PK nails found at the outside pavement edge.

At the time of suspension of the site there were no unresolved problems with any of the sensors. The plots from ONSFIELD, MOBFIELD, and SMPCHECK follow expected trends and produce expected values.



- Total Depth of Piezometer: 4.29m
- Distance of Piezometer Below Ground Level: 152mm

Figure 1.- Location for Seasonal Monitoring Instrumentation at GPS 331001

SUMMARY OF SMP DATA COLLECTION TO DATE

Agency Code
 LTPF Section I.D.
 Location

1 3 3
 1 0 0 1 1
 Concord, New Hampshire

Test Date dd/mm/yy	Visit Ident./ Code	ONSITE Data		MOBILE Data		Manual Data				FWD Data			Distress Data		Profile Data		Comments						
		Fav Temp.	Ambient Temp.	Rainfall	Moisture (TDR)	Frost Depth (Resist.)	Backup Pev. Temp.	Backup Moisture (TDR)	Frost Depth 2 - point	Frost Depth 4 - point	Water Table	Surface Elev.	Joint Open.	Joint Fault.	Surface Layer Temp.	OVP		ML	PE	Manual	PASCO	Profiler	Dipstick
14-Oct-93	A	X	X	X	X	X		X	X	X	X				3	3							On-site data only
28-Dec-93	B	X	X	X	X	X		X	X	X	X				3	3							On-site data only
10-Feb-94	A	X	X	X	X	X		X	X	X	X				3	3							On-site data only
03-Mar-94	B	X	X	X	X	X		X	X	X	X				4	4							On-site data only
21-Mar-94	C	X	X	X	X	X		X	X	X	X				4	4							Mobile TDR error
14-Apr-94	D	X	X	X	X	X		X	X	X	X				4	4						X	On-site data only
05-May-94	E	X	X	X	X	X		X	X	X	X				4	4							Mobile TDR error
28-May-94	F	X	X	X	X	X		X	X	X	X				4	4							Mobile TDR error
23-Jun-94	G	X	X	X	X	X		X	X	X	X				3	3						X	Mobile TDR error
21-Jul-94	H	X	X	X	X	X		X	X	X	X				4	4							Mobile TDR error
16-Aug-94	I	X	X	X	X	X		X	X	X	X				3	3							Mobile TDR error
22-Sep-94	J	X	X	X	X	X		X	X	X	X				3	3							Mobile TDR error
20-Oct-94	K	X	X	X	X	X		X	X	X	X				3	3							Mobile TDR error
17-Nov-94	L	X	X	X	X	X		X	X	X	X				2	2							Mobile TDR error
15-Dec-94	M	X	X	X	X	X		X	X	X	X				3	3							Mobile TDR error
24-Jan-95	A	X	X	X	X	X		X	X	X	X				3	3							Mobile TDR error
21-Feb-95	B	X	X	X	X	X		X	X	X	X				2	2							Mobile TDR error
18-Mar-95	C	X	X	X	X	X		X	X	X	X				3	3							Mobile TDR error
30-Mar-95	D	X	X	X	X	X		X	X	X	X				2	2							Mobile TDR error
27-Apr-95	E	X	X	X	X	X		X	X	X	X				3	3							Mobile TDR error
11-May-95	F	X	X	X	X	X		X	X	X	X				4	4							Mobile TDR error
01-Jun-95	G	X	X	X	X	X		X	X	X	X				3	3						X	On-site data only problem with power source for TDR close-out
28-Jun-95	H	X	X	X	X	X		X	X	X	X				7	7							On-site data only problem with power source for TDR close-out



Instrumentation Hole, Seasonal Site 331001 NH, June 1995, During Suspension Preparation Activities



Instrumentation Hole, Seasonal Site 331001 NH, June 1995, During Suspension Preparation Activities