

19 May 2003

Jack Springer  
Federal Highway Administration (HRDI-13)  
Pavement Performance Division - LTPP  
Turner-Fairbanks Highway Research Center  
6300 Georgetown Pike, Room F-209  
McLean, Virginia 22101-2767

Subject: SMP Round I Suspension Report - Test Section 484143/48SD

Dear Jack,

The seasonal section 484143/48SD, which is located on US-90, was suspended on 28 June 1995. This GPS-4 section is located near Beaumont, Texas, and belongs to cell 10 (wet-no freeze zone) of the Experiment Design.

### **Problems Encountered**

One of the main problems encountered was faulty sensors. A list of all other problems encountered is provided below.

1. The ONSITE file for January 1994 was corrupted and unreadable.
2. The MOBILE file for February 1994 was corrupted and unreadable.
3. The ONSITE file for May 1994 was missing.
4. The MOBILE file for December 1994 was corrupted and unreadable.
5. The MOBILE and ONSITE data could not be collected on 5 June 1995 as the result of rain; however, it was collected on 8 June 1995.
6. FWD testing and the manual distress surveys were not conducted in October 1994 due to rain.

### **Suspension Activities**

The following activities were carried out per Directive SM-8.

1. Inspection and numbering of the Time Domain Reflectometry (TDR) sensor cables.
2. Final water table depth measurements were taken, followed by sealing the end of the well pipe. The access cover was inspected to determine if any repairs were needed and repairs were carried out if necessary. Drainage conditions were inspected to ensure that no water would be accumulated.
3. Condition assessment of the instrumentation hole per Directive SM-4, followed by repairs that were found to be necessary.
4. Section markings were made to help locate deflection test points and elevation survey points.
5. The ONSITE data was uploaded and the air temperature sensor, rain gauge and support pole were all dismantled. Power to the CR10 was turned off and the sensor wires were disconnected from the panel board; the panel board was then disconnected.
6. Anti-corrosion compounds were applied to the TDR BNC connectors, electrical resistivity connector and MRC temperature lead wires, and all the wires and connectors were sealed in plastic bags and placed in the cabinet.
7. Cabinet locks were inspected and replaced where necessary.
8. Photographs of the instrumentation hole, access trench and distresses occurring in the SMP monitoring zone were taken.

The following supplemental information is attached to this report.

1. Summary of the SMP measurements.
2. Color copies of site photographs taken during suspension preparation activities.
3. Site layout schematic.

Should you have any questions or comments regarding this report, or require further information, please contact me.

Sincerely,

Mark P. Gardner, P.E.  
Project Manager, SRSC  
MPG:dmj  
Attachment: As stated.

cc.w/Att: Gonzalo Rada, MACTEC-MD

Figure 1. Site Layout Schematic