

- The old loop joint hole was corrected using rubber in the joint and Ebond G-100 (left over from frame replacement) grout to fill the large slot left after the old material was removed

Action Items:

Item	Action Required	Ownership
1.		