

**- Site Service Report -**

Date: June 10, 2009

**IRD SO.: 10785**

**IRD Contract No.:**

**From: Jorge Rubio**

**To: ESS**

**State: KANSAS**

**Project Name/Location: FTTP SITE I-70 WEST BOUND MI 287-5**

**Service Date(s): February 04, 2009**

**Temp: 40°F**

**Job Description: Temperature Sensor**

**Work Completed:**

- Temperature sensor has been attached on the back of the pull box cover, see attached picture.
- Called Rey to make sure temperature sensor was working as expected.
- According to Ray it was sensing 8°C
- Loops and bending plate working as expected.



**Parts Used: None.**

Part Name	Part Number	Quantity Used

**Mileage: 512 round trip**

**Hours Worked: 2 hours onsite, 8 hours travel.**

**Total: 10 hours.**

**Notes:**

**Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		