



INTERNATIONAL ROAD DYNAMICS INC.
 702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9
 Phone (306) 653-6600 Fax: (306) 242-5599

- Site Service Report -

September 7, 2007

IRD SO#: 10785I
From: Brent Eckhart
Project Name: Danville LTTP
Project Location: Danville, VA RT.29 SB
Service Date(s): 6-21-07
Weather: Clear and hot

IRD Ref: 10785I
To: ESS

Job Description: Do a site inspection

Work Completed: Site inspection completed. Cabinet was fairly clean but cleaned a little dust out with some canned air and a dust rag. Had an off site technician dial in remotely after my measurements were taken to ensure that the unit was operating properly and to test the operation of the modem.

Mileage / Travel Time:
 3 Hrs to site.

Time Spent on Site:
 2 Hrs total.

Notes:
 The site was in good condition. The road sensors appeared to be in good visible condition. The loops were sealed well. No excess coming off of the bending plates. Sensor homeruns and shoulder stubbing looked well sealed and in good condition as well. The cabinet was very clean overall.

Action Items:

Item	Action Required	Ownership
1.		