



**INTERNATIONAL ROAD DYNAMICS INC.**  
 702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9  
 Phone (306) 653-6600 Fax: (306) 242-5599

**- Site Service Report -**

June 10, 2009

**IRD SO#: 11013**  
**From: Brent Eckhart**  
**Project Name:LTTP**  
**Project Location:Danville VA, SB RT29**  
**Service Date(s):12/17/2008**  
**Weather: Overcast, cool, damp**

**IRD Ref:**  
**To:**

**Job Description:**  
 To perform scheduled site inspection and electrical checks.

**Work Completed:**  
 Completed electrical checks. Everything was in spec.  
 Cabinet was clean, and dust free.  
 Ensured all sensor connections and terminations were tight.  
 Called into to head office to dial into onsite modem and connect to electronics. This ensures that modem does work and that vehicle records were being made after I had removed and reinstalled a few connections.  
 A physical inspection of the road sesors showed that sensors were in overall good condition. Silicone was missing on some bolts. The concrete slab in which the the sensors and loops are installed are showing signs of minor hair line cracks.  
 Bending plate sensors also sound good as traffic travels over them.  
 Junction box aprons are also showing signs of cracking. Nothing significant that would indicate problems with the overall structural integrity of the box itself though.

**Mileage / Travel Time:**  
 1 hr

**Time Spent on Site:**  
 1.5 hrs

**Notes:**

**Action Items:**

Item	Action Required	Ownership
1.		