

9/24/13 BAT
(previous survey 9/24/12)


File M104 5/5/2014 DAV

CELL 4
0 - 50 ft

10/21/2014 DAV
same minor adjustments
DISTRICTS

1120+35

1120+85




5/5/2014 DAV

CELL 4
50 - 100 ft

1120+85

1121+35




5/5/2014 DAV

CELL 4
100 - 150 ft

1121+85

1121+85




5/5/2014 DAV

CELL 4
150 - 200 ft

1121+85


1122+35



CELL 4
200 - 250 ft

1122+35


1122+85



CELL 4
250 - 300 ft

1122+65


1123+95



CELL 4
300 - 350 ft

1123+85

1123+85




probably a tear from vehicle?
looks like R_L

CELL 4
350 - 400 ft

1123+85


1124+35



CELL 4
400 - 450 ft

1124+35

1124+85



CELL 4
450 - 500 ft

1124+85

1125+35

