

3/27/2014 DAN

No New distress

9/27/13 BAT

(previous survey 10/5/12)

File LV21

Cell 36 | Cell 37

Cell 37
0 - 50 ft

86+24

JT 1034

JT 1035


JT 1036

JT 1037

JT 1038

86+74


Diamond grinding blew out
sealant in Outside Lane



Cell 37
50 - 100 ft

86+74

87+24




Cell 37
100 - 150 ft

87+24

87+74

0' JT 1043 10' JT 1044 20' JT 1045 30' JT 1046 40' 50'


PANEL 8



Cell 37
150 - 200 ft

87+74


88+24



Cell 37
200 - 250 ft

88+24

88+74



Cell 37
250 - 300 ft

88+74

89+24

JT 1055

JT 1056

JT 1057

JT 1058

0'

10'

20'

30'

40'


50'

19

20

21

22



6

Cell 37
300 - 350 ft

89+24

89+74

JT 1059


JT 1060

JT 1061

JT 1062

JT 1063


0' 10' 20' 30' 40' 50'



Cell 37
350 - 400 ft

89+74

90+24



Cell 37
400 - 450 ft

90+24


90+74

JT 1068

JT 1069

JT 1070


JT 1071



Cell 37
450 - 500 ft

90+74

91+24



Cell 37
500 - 550 ft

Cell 37 Transition

91+24

91+74

JT 1076

JT 1077

JT 1078

JT 1079

0' 13'

10'

20'

30'

40'

50'

