

3/27/2014 DAN

Raining light - water collecting in out, inside lane

no other distress

5-8-2015 BJB no addl distress


CELL 34
0 - 50 ft

File LV18

69+45

69+95


5-7-2015
rubble strip added
to both sides by center line



CELL 34
50 - 100 ft

69+95


70+45



CELL 34
100 - 150 ft

70+45


70+95



CELL 34
150 - 200 ft

70+95


71+45



CELL 34
200 - 250 ft

71+45


71+95



CELL 34
250 - 300 ft

71+95

72+45




6

CELL 34
300 - 350 ft

72+45


72+95



CELL 34
350 - 400 ft

72+95


73+45



CELL 34
400 - 450 ft

73+45

73+95



CELL 34
450 - 500 ft

73+95

74+45

