

3/27/2014 DAV

9/27/13 BAT

(previous survey 10/5/12)


5/28/2015 BB Cell 36 Cell 37
no changes

No New distress
11/23/2015 LCP
NND

File LV21

Cell 37
0 - 50 ft


Diamond grinding blew out
sealant in Outside Lane



Cell 37
50 - 100 ft

86+74

87+24



Cell 37
100' x 150' ft

87+24

PANEL 8

87+74

JT 1043

JT 1044

JT 1045

JT 1046

0'

10'

20'

30'

40'

50'

12' Outside Lane

12'

8'

4'

CL

4'

8'

12' Inside Lane

0'

10'

20'

30'

40'

50'

Seal H

Seal H

Seal H

Seal H


Seal L

Seal L

Seal L

Seal L

Cell 37
150 - 200 ft



Cell 37
200 - 250 ft

88+24


JT 1051

JT 1052


JT 1053

JT 1054

88+74



Cell 37
250 - 300 ft



Cell 37
300 - 350 ft

89+24

JT 1059

20

0'

JT 1060

24

10'

JT 1061

28

20'

JT 1062


28

30'

JT 1063

89+74

50'




FWD 25

Cell 37
350 - 400 ft

89+74

90+24



Cell 37
400 - 450 ft

90+24

90+74

JT 1068

JT 1069

JT 1070

JT 1071

0'

10'

20'

30'

40'

50'

12'

12' Outside Lane

Seal
H

Seal
H

Seal
H

Seal
H

CL

CL

Seal
L

Seal
L

Seal
L

Seal
L

12' Inside Lane

0'

10'

20'


30'

40'

50'

Small
cansister
above

Cell 37
450 - 500 ft



Cell 37
500 - 550 ft

Cell 37 Transition

91+24

JT 1076

10'

JT 1077

20'

JT 1078


30'

JT 1079

40'

91+74

50'



//