

File ML13
Cell 162

CELL 162
0 - 50 ft

1157+87
JT 5075

5/6/2014 DAY
5/13/2015 R18
All joints sealed.

JT 5080

30'


40'

50'

10/27/2014 DAY
winter cleaning
near access ports
in areas @ it 5100

1158+37

10/6/2015 NDO REP
5/16/2016 REP



Surface texture changes
reported near
no add'l distress


CELL 162
100 - 150 ft

1158+87

JT 5092

JT 5095

1158+87
JT 5100



CELL 162
200 - 225 ft

Cell 162 Cell 163


1159+87

JT 5110

1160+15
JT 5114

JT 5115

1160+87



File ML14
Cell 163

CELL 163
0 - 50 ft

5/6/2014 DVV

10/27/2014 DVV
NO EXAMINED
DISTRESS


NO DISTRESS. All JTs sealed.

JT 5115 → 5/13/2015 R/B


10/6/2015 ASD JCP
5/16/2016 LEP
NO NEW DISTRESS

1160+15
JT 5114

1160+65



CELL 163
100 - 150 ft



CELL 163
200 - 225 ft

End Cell 163

1162+15

JT 5148

JT 5150

1162+43
JT 5152

1162+65

