

7/12/2016 LR  
11/23/2015 LCP  
No New Distress

9/27/2013 B+T

File LV17

(Previous Survey 10/3/2012)

CELL 33  
0 - 50 ft

63+75

3/27/2013 VAN

5-7-2015 BVB  
5-20-2015 MMD

20'

30'


40'

50'

64+25

5-7-2015  
sample strip removed for  
analysis


Shows Oxidization and mild corrosion - drying out on surface



CELL 33  
50 - 100 ft

64+25

64+75




64+75

CELL 33  
100 - 150 ft

Centerline  
Rumblestrip  
Stops @ 65-00

66+25



CELL 33  
150 - 200 ft

65+25

0'

10'

20'


30'

40'

50'

65+50

65+75




CELL 33  
200 - 250 ft

65+75

66+00

66+25




CELL 33  
250 - 300 ft

66+25

66+50

66+75




CELL 33  
300 - 350 ft

66+75

67+25

67



CELL 33  
350 - 400 ft

67+25

0'

10'

20'


30'

40'

50'

67+50

67+75



CELL 33  
400 - 450 ft.

48



CELL 33  
450 - 500 ft

68+25

0'

10'

20'

30'

40'

50'

68+75

