

3/27/2014 DAD

9/07/13 BAT

(previous survey

10/5/12)

No New distress

11/27/2015 KGF

7/12/16 LT

Cell 37
0-50 ft

File LV21

86+24

JT 1034

5/28/2015 BJB Cell 36 Cell 37
no changes

JT 1035

10'

20'

JT 1036

30'

JT 1037


40'

JT 1038

50'

Diamond grinding blew out
sealant in Outside Lane

86+74



Cell 37
50 - 100 ft

88+74

87+24

JT 1039

JT 1040

JT 1041

JT 1042

0'

10'

20'

30'

40'

50'

12' Outside Lane

12' Inside Lane

0'


10'

20'

30'

40'

50'



Cell 37
100' x 150 ft

87+24

JT 1043


JT 1044

PANEL 8


JT 1045

JT 1046

87+74



Cell 37
150 - 200 ft



Cell 37
200 - 250 ft

88+24

JT 1051

0' 14

JT 1052

10' 5

JT 1053

20' 19

JT 1054


30' 1

40'

8

88+74

50'



Cell 37
250 - 300 ft

88+74

JT 1055

0'

10'

JT 1056

20'

JT 1057


30'

JT 1058

40'

50'

89+24



6

300 - 350 ft


89+74

JT 1060

JT 1061

JT 1062


JT 1063



Cell 37
350 - 400 ft

89+74

90+24



Cell 37
400 - 450 ft

90+24


JT 1068

JT 1069

JT 1070

JT 1071

90+74



Cell 37
450 - 500 ft

90+74

JT 1072

JT 1073

JT 1074

JT 1075

91+24

0' 37

10' 36

20'

31


30'

38

40'

39

50'



Cell 37
500 - 550 ft

Cell 37 Transition

91+24

JT 1076

10'

JT 1077

20'

JT 1078

30'

JT 1079

40'

91+74

50'

