

its unsealed.

CELLS 114-914
0-50 ft

10/27/2014 DAV
5/18/2016 KCP

50 ft
7/5/2016 AEI
notable faulting throughout.
-12/2015 R/R

Transition Cell 14.

5/18/2016 KCP

JT 4139

JT 4140


JT.4141


JT:4142

JT-4143

JT 4144

J14745

 $1189+40$ 



1189+90

JT 4155

JT 4156

JT 4157

JT 4158

JT 4159

JT 4160

JT 4161

JT 4162

JT 4163

JT 4164

JT 4165

JT 4166

JT 4167

JT 4168

Cell 214 Cell 314

CELLS 214-314
100 - 150 ft

June 2015
PATCH REPLACED
WITH LARGER PATCH
65' SQ on SURFACE
80' TOTAL

1190+40

CELL 314
200 ÷ 250 ft

1190+90-

JT 4971

JT 4172

JT 4173.

JT-4174

JT 4175

JT 4176

JT 4177

JT 4178

JT 4179

Q.


10'

20'

301

40'

5.0'



4

CELLS 514-614
300 - 350 ft

Cell 514 | Cell 614

1191+90

JT 4188

JT 4189

JT 4190


JT 4191

JT 4192

JT 4193

1192+40

core MISSING GROUT



NO

2

1192+90

cracked concrete
missing 16" x 4"

JT 4199

CELLS 614-814
400 ~ 450 ft

Cell 614 | Cell 714

JT 4200

JT 4201

JT 4202


JT 4203

JT 4204

1193+40

Cell 714 | Cell 814

FAULT



423'

447

