

4/25/17 LCP
4/24/18 LCP

10/27/2014 DAN

MINOR CRACKING
NEAR ACCESS PORTS
IN GRAB @ JT 5100

1158+37

10/27/2014 LCP
5/16/2016 KEP

JT 5080

CELL 162
0 - 50 ft

5/6/2014 DAN

5/13/2015 BJB

All joints sealed.

1157+87
JT 5075

Replaced
10/17

0 CB M CB H 2

20' 3


A

30'

7
10/17


40' 6

50'



Surface Texture Changes
Potholes, wear
no add'l distress

CELL 162
50 - 100 ft



CELL 162
150 - 200 ft

1:159+87
JT 5101

25

1:159+87

JT 5105

0'  10'

10'

26

27

20'

28

30'


29

20

31

50'

32



4

