

5 January 2004

Jack Springer
Federal Highway Administration (HRDI-13)
Pavement Performance Division - LTPP
Turner-Fairbanks Highway Research Center
6300 Georgetown Pike, Room F-209
McLean, Virginia 22101-2767

Subject: SMP Suspension Report - 010101/01SB

Dear Jack,

The seasonal section 010102/01SB, which is located on US-431, was suspended on 25 April 1998. This SPS-1 section is located about 4.51 km west of CR-183 in Opelika, Alabama and belongs to cell 10 (wet-no freeze zone) of the Experiment Design. This site has remained out-of-service since its April 1998 suspension. All that remained were the towers and cabinets.

Problems Encountered

No problems were encountered.

Suspension Activities

1. Removal of the towers and cabinets; the TDR cables cut off below ground level and buried.
2. Sealed piezometer well.

Should you have any questions or comments regarding this report, or require further information, please contact me.

Sincerely,

Mark P. Gardner, P.E.
Project Manager, SRSC
MPG:dmj
cc: Gonzalo Rada, MACTEC-MD