



**INTERNATIONAL ROAD DYNAMICS INC.**  
 702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9  
 Phone (306) 653-6600 Fax: (306) 242-5599

**- Site Service Report -**

May 3, 2007

**IRD SO#: 10407D**  
**From:** Greg Felsing  
**Project Name:** AZ LTTP  
**Project Location:** I-10 @ MP 108.5 EB  
**Service Date(s):** Mar27.-28,2007  
**Weather:** sunny 75F

**IRD Ref:**  
**To:** Sheri Perrett

**Job Description:** Frame replacements on LTTP site. Currently they are too high to allow for proper signal processing.

**Work Completed:** Replace both frames in Lane #1, and replace downstream bending plate as the lead-in cable was pinched during re-installation. (This was replaced Apr5,2007)  
 Calibrated Apr 17,2007. Results were successful.

**Work Remaining:** Firmware upgrade to be completed this week.

**Parts Used:** 2 frames, 1 bending plate

**Mileage / Travel Time:** 132 miles 3 hours 3 separate trips.

**Time Spent on Site:** 20 hours

**Notes:**

**Action Items:**

Item	Action Required	Ownership
1.		