



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: September 26, 2012

IRD Sales Order:

To: Cindy Manti

From: Steven Schroeder

Project Name/Location: Delaware LTPP

Service Date(s): 7/13/09- 7/14/09

Job Description: Perform site inspection and Check communications.

Work Completed:

7/13/09- Drove to Lancaster,PA

7/14/09- Finished drive to site. Arrived on site at 10:40am. I performed the site inspection. Sensors tested ok. Loops should be respliced on next visit they are getting a low shield resistance. I then took a couple site pictures and cycled the power on the modem. I called IRD main office and had Labeed Dial the site and confirm operations. I left site at 11:20 am and drove home.

K1= 14.5nf 10¹¹ohm resistance

K2= 13.9nf 10¹¹ ohm resistance

L1= 1.8 ohm 196uH 1.3M ohm/shield

L2=1.9 ohm 267uH 1M ohm/shield

Work Remaining:n/a

Schedule Include Estimate to Complete (on-track, ahead, behind): n/a

Parts Used:

n/a

Pre-mature Equipment Failure:

Mileage / Travel Time:

850 miles

17 hours

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		