



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Phone (306) 653-6600 Fax: (306) 242-5599

**- Site Service Report -**

October 4, 2012

**IRD SO#: 11167**

**From: Jorge Rubio**

**Project Name: LTPP KANSAS**

**Project Location: I-70 Westbound - MI 287.5**

**Service Date(s): November 02, 2010**

**Weather: 31° C 88° F**

**IRD Ref:**

**To: ESS**

**Job Description: Maintenance**

**Work Completed:**

- Cleaned cabinet
- Tested bending plate:  
preload on cell #1 1.2mv  
preload on cell #2 4mv
- Loop #1 megged out 338MΩ, 1.7Ω
- Loop #2 megged out 370MΩ, 1.8Ω
- Checked backup battery voltage (13.2VDC)
- Checked ACV 123.4
- Checked timer, modem and all Isinc components
- System restarted and tested
- Monitored vehicles for 10 minutes.
- Left FTTP site working.
- The temperature sensor still firmly attached to the junction box cover.
- Both bending plates solid, no sounds detected as traffic goes by.
- Called Labeed to check remote communications.
- General condition: Very good.

**Work Remaining: None**

**Parts Used: None**

**Mileage / Travel Time: 486MI / 8 hrs**

**Time Spent on Site: 2 hours**

**Notes:**

**Action Items:**

| Item | Action Required | Ownership |
|------|-----------------|-----------|
|      |                 |           |

