



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Phone (306) 653-6600 Fax: (306) 242-5599

- Site Service Report -

June 9, 2009

IRD SO#:

IRD Ref:

From: Jorge Rubio

To: ESS

Project Name: LTTP Bemidji, MN

Project Location: Highway 2 Mile 91.5

Service Date(s): November 13, 2008

Weather: 39° Fahrenheit

Job Description: Maintenance

Work Completed:

- Loops, kistlers, piezos and cabinet visually inspected (good condition)
- iSINC components working as expected
- Powered down iSINC to remove each card and cleaned slots and connectors
- Each ferrule connectors removed to check each sensor.
- Installed new ferrule connectors.
- Powered back on the iSINC and observed LED activity (working right)
- Connected laptop and observed activity (working right)
- Vehicle records displayed as expected.
- Left iSINC running as expected.

Work Remaining: None

Parts Used: Ferrules

Mileage / Travel Time: 486MI / 8 hrs

Time Spent on Site: 3 hours

Notes:

Action Items:

Item	Action Required	Ownership
1.	Install new backup battery	JR