



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 [www.irdinc.com](http://www.irdinc.com)

## - Site Report -

**Date: January 10, 2012**

**IRD Sales Order: 11167**

**To: Cindy Mantie**

**From: Bryan Knight**

**Project Name/Location: LTPP NM 2 I-10 E mp 49.5**

**Service Date(s): June 13, 2011**

**Job Description: Swap Out Reno LSM for iSinc LSM**

**Work Completed:**

- **Installed new iSinc LSM in place of old Reno style LSM. (Picture Attached)**
- **Relocated LSM ribbon cable to top connector of the SIOP.**
- **Configured the loops to the new LSM UID.**
- **Verified new Loop Card is functioning normally.**
- **Logged on and monitored traffic system performance OK. No loop 'ghost' triggers were observed coming from the traffic in the adjacent lane.**



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 [www.irdinc.com](http://www.irdinc.com)



**Work Remaining: None**

**Schedule Include Estimate to Complete (on-track, ahead, behind):**

**Parts Used: One (1) iSinc LSM Card**

**Pre-mature Equipment Failure:**

**Mileage / Travel Time: Total Travel: 8hrs Total Onsite: 1hr**

**Safety Concerns:**

**Issues Related to Sub-Contractors:**



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43<sup>rd</sup> Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 [www.irdinc.com](http://www.irdinc.com)

**Other Notes:**

**Action Items:**

| Item | Action Required | Ownership |
|------|-----------------|-----------|
| 1.   |                 |           |
| 2.   |                 |           |
| 3.   |                 |           |
| 4.   |                 |           |