



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43rd Street East, Saskatoon, SK, Canada,

Phone: (306) 653-6600 Fax: (306) 242-5599

**- Site Service Report -**

Date: September 26, 2012

**IRD SO.:** 10667

**IRD Contract No.:**

**From:** Steven Schroeder

**To:** Cindy Mantie

**Project Name/Location:** PA LTPP

**Service Date(s):** 3-17-2010

**Job Description:** Replace subrack and upgrade to a W3.

**Work Completed:**

**3-17-10**

Drove to site. Shut down system at 3am and replaced subrack. Installed all cards into new rack and verified operation. The new rack solved the PSM issue. I was unable to get a direct connection to WCU-II so I started the switch to the W3. I installed all parameters manually, after copying them from the WCU-II, into the W3. I then watched traffic and verified operation. I connected the modem with the ribbon cable supplied to the backplane on the W3 slot. I also left the TGM Card in without the fuses as per IRD Instructions.

The WCU-II removed was serial #080913530

New W3 installed was serial #091119011

Site was operational by 5:40 AM.

Drove Home

**Drive Time: 6.5 hrs**

**Mileage: 360 miles**

**Parts used:**

1- W3 serial #091119011

1- subrack

**Notes:**



**INTERNATIONAL ROAD DYNAMICS INC.**

702 - 43rd Street East, Saskatoon, SK, Canada,

Phone: (306) 653-6600 Fax: (306) 242-5599



**Action Items:**

Item	Action Required	Ownership
1.		
2.		
3.		
4.		