



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: October 5, 2012

IRD Sales Order: 11167

To: Chad Fuston

From: Shawn Brown, Bruce Myers, Cindy Matie

Project Name/Location: Jackson LTPP (TN) / I-40 Mile Post 91.6

Service Date(s): December 11th, 2009

Weather: Sunny, clear, 38F Temp

Job Description:

- Performed routine site maintenance

Work Completed:

- Check Loop Function (Megger Test)
- Inspect In-road Sensors (Grouts and Sealants)
- Inspect Junction/Pull Boxes
- Open Electronics And Clean/Dust
- Clean All I/F Cards
- Check Mains Voltage Level
- Check Earth Grounding
- Clean Cabinet Interior
- Check Cabinet Seal
- Check Function Of Fan / Heater / Air Con.
- Check Status Of Telephone Line
- Check Modem Function
- Check Batteries
- Check Solar Charging Current

Work Remaining:

- There is a small piece of grout missing from the upstream Kistler in the right lane (slow lane) on the east bound side. A lane closure and warm temperature is needed to perform the repair.

Schedule Include Estimate to Complete (on-track, ahead, behind):

- On-track

Parts Used: none

Pre-mature Equipment Failure:

- None

Mileage / Travel Time:

- 339 miles / 5 Hrs (one way)

Safety Concerns:

- None noted

Issues Related to Sub-Contractors:



TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- None

Other Notes: even though the Kistler sensor is missing a piece of grout, it is still functioning properly.

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com






TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com






TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com






INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com



West Bound Side.



TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com



West Bound Side.



TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com



East Bound Side.



TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com




East Bound Side.



TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com



Kistler Damage.