



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East, Saskatoon, SK, Canada,

Phone: (306) 653-6600 Fax: (306) 242-5599

- Site Service Report -

IRD SO.: 11167

IRD Contract No.:

From: Brent Eckhart

To:

Project Name/Location:LTTP. Danville VA, RT 29 SB

Service Date(s):6-29-2009

Job Description:

Perform bi-annual site inspection and electrical readings.

Repalce current loop card with a newer LSM card as per instructed by head office

Work Completed:

Performed electrical measurements.

Performed site inspection.

Swapped out the the loop card for the iSINC LSM card. I needed Rey Castro's help remotely from Saskatoon to configure the system and program the card with the proper firmware.

Through dialup, we confirmed that the modem was working, the terminations that I had removed for the electrical measurements were good and also, the new LSM was operating

Work Remaining:

Monitor site remotely to ensure LSM continues to function properly

Parts Used:

1 LSM card P/N 195242

Mileage / Travel Time:

3 hrs

Notes:

Cabinet was clean.

Light was working

Axle sensors looked and sounded good when vehicles rolled over. The bolts are still protected from silicone

Home runs and junction box lids and aprons are in good shape.

The grass on site is getting a little long and should be cut.

The concrete road surface has very small hairline cracks in the loop locations. Nothing to worry about as of yet.

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		