



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East, Saskatoon, SK, Canada,

Phone: (306) 653-6600 Fax: (306) 242-5599

- Site Service Report -

IRD SO.: 11167

IRD Contract No.:

From: Brent Eckhart

To:

Project Name/Location: LTTP, Danville VA, RT 29 SB

Service Date(s): 7-7-09

Job Description:

Site visit required to determine why dialin attempts result in a busy tone from modem

Work Completed:

I power cycled the modem and had Rey Castro from head office attempt to dial in. Busy tone.

I removed the phone cable from modem and had Rey attempt again. Busy tone.

I measured the voltage on the phone line with no call, and it was sitting at 12VDC. I believe it should be anywhere between 24 and 48 VDC

I put a telephone on my phone jack in the cabinet and did not have a dial tone.

Work Remaining:

A site visit by the phone company is required. Rey will inform project manager Cindy Mantie and have her coordinate this .

Parts Used:

Mileage / Travel Time:

3 hrs

Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		