


1228+05

1228+00

1227+55



CELL 20


ML10-F-20

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999

1227+55

1227+05



CELL 20

ML10-F-20

DISTRESS SURVEY - OCTOBER 14-22, 1999

LABORATORY

1227+05

1227+00

1226+55

100'

110'

120'

130'

140'

150'


CELL 20

ML10-F-20


SENSOR AREA

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999



DISTRESS SURVEY - OCTOBER 14-22, 1999



1226+05

1226+00

1225+55

200'

210'

220'

230'

240'

250'

-12'

-8'

-4'

0

4'

8'

12'

CELL 20


ML10-F-20

✓-R

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999


DISTRESS SURVEY - OCTOBER 14-22, 1999



1225+05

1225+00

1224+55



CELL 20


ML10-F-20

INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999

1224+55

1224+05



CELL 20

ML10-F-20


DISTRESS SURVEY - OCTOBER 14-22, 1999

1224+05

1224+00

1.2

1223+55



CELL 20

ML10F-20

DISTRESS SURVEY - OCTOBER 14-22, 1999

1223+55

1223+05

450'

460'


470'

480'

490'

500'

CELL 20
ML10-F-20



INSPECTION

DISTRESS SURVEY - OCTOBER 14-22, 1999