



17 not fault
 cracks dislocation
 lots of faulting in the
 hole in the




CELL 17

DISTRESS SURVEY – OCTOBER 22-26, 2001




CELL 17


DISTRESS SURVEY – OCTOBER 22-26, 2001




DISTRESS SURVEY – OCTOBER 22-26, 2001



DISTRESS SURVEY – OCTOBER 22-26, 2001




DISTRESS SURVEY – OCTOBER 22-26, 2001



DISTRESS SURVEY – OCTOBER 22-26, 2001


1207+65

1207+15



CELL 17


DISTRESS SURVEY – OCTOBER 22-26, 2001



DISTRESS SURVEY – OCTOBER 22-26, 2001

1208+65

1208+15



CELL 17

DISTRESS SURVEY – OCTOBER 22-26, 2001