


$$CL_L = 50$$

CELL 35

0-50 ft

79+37



DISTRESS SURVEY

~~12/29/04~~

Tim

~~5/17/15~~

10/26/05


$$6L = 8/22$$
$$4aL = 3$$


CELL 35
50-100 ft

$$6L = 9/46$$

$$4aL = 3$$

$$CL_L = 50$$



$$6L = 9/49$$

DISTRESS SURVEY
12/29/04




CELL 35

100-150 ft

$$GL = 11/63$$

$$CLL = 50$$



DISTRESS SURVEY
12/29/04

$$GL = 17/77$$

$$4aL = 3$$



CELL 35

150-200 ft

6L = ~~10/54~~ 9/38

6L = 1-1/13


CLL = 50

4aL = 9

4aM = 23

4bL = 7

77+87



6L = 22/76

4aL = 17

DISTRESS SURVEY
12/29/04




CELL 35

200-250 ft

6L = 10/39

4aL = 24

CLL = 50



6L = 12/44

4aL = 24

DISTRESS SURVEY
12/29/04




250-300 ft

$$CL_L = 50$$

76+87

300'


-12'


$$4aL = 15$$
DISTRESS SURVEY
12/29/04

SENSOR AREA



300-350 ft

$$CL_L = 50$$
**DISTRESS SURVEY**
12/29/04
$$46L = 3$$


CELL 35

350-400 ft


$$6L = 6/15$$

$$6M = 3/33$$

$$CLL = 50$$

$$4aL = 75$$

$$4aM = 8$$



$$6L = 18/60$$

$$4aL = 3$$

DISTRESS SURVEY
12/29/04



CELL 35

400-450 ft

$$6L = 8/41$$


$$T_M = 14$$

$$6M = 1/10$$

$$CL_L = 50$$

$$4aL = 48$$

$$4aM = 55$$



$$6L = 9/50$$

$$4aL = 15$$

DISTRESS SURVEY
12/29/04



CELL 35


450-500 ft

$$F_M = 56$$

$$F_L = 36$$

$$CL = 5/18$$

$$CL_L = 42$$



DISTRESS SURVEY
12/29/04

$$CL = 4/23$$