

~~9/8/2010~~
~~MRC~~

~~4/25/2011~~
~~MRC~~


10/27/11
TRC

Cell 37
0 - 50 ft

Cell 37 Cell 54

trans. Cell 37

Diamond grinding blew out
sealant in Outside Lane



Cell 37
50 - 100 ft

* new sealant in OWP, OK
about 5' in from shld.
(not whole lane)
most jts

86+74


87+24

JT 1039

JT 1040

JT 1041

JT 1042



Cell 37
100 - 150 ft

87+24


87+74

JT 1043

JT 1044

JT 1045

JT 1046



Cell 37
150 - 200 ft

67+74


68+24

JT 1047

JT 1048

JT 1049

JT 1050



Cell 37
200 - 250 ft

88+24


88+74

JT 1051

JT 1052

JT 1053

JT 1054



Cell 37
250 - 300 ft

88-74


89+24

JT 1055

JT 1056

JT 1057

JT 1058



Cell 37
300 - 350 ft

89+24

89+74


JT 1059

JT 1060

JT 1061

JT 1062

JT 1063



Cell 37
350 - 400 ft

89+74


90+24

JT 1064

JT 1065

JT 1066

JT 1067



Cell 37
400 - 450 ft

90+24


90+74

JT 1068

JT 1069

JT 1070

JT 1071



Cell 37
450 - 500 ft

90+74


91+24

JT 1072

JT 1073

JT 1074

JT 1075



Cell 37
500 - 550 ft

Cell 37 Transition

