

(previous survey 9/24/12)

5/5/2014 DXN

5/5/2014 DAV
Spring 2015 MIKEA


CELL 4
0-50 ft

10/21/2017 DAY
same minor additional

D(Street) 8-20-2015 BJB

1120+85
FWD 2

- fwd 1.5



5/5/2014 DAN

CELL 4
50 - 100 ft


1121+00

FWD 2

1120+35

1121+35


FWD 3



ALPS

CELL 4
100 - 150 ft


5/5/04 DAV



15/5/2014

22

1122+35
FWD
5
50



5


CELL 4
200 - 250 ft

1122+35

FWO 5

1122+85

FWO 6




50

CELL 4
250 - 300 ft

1123+00

1122+65
FWD 6

1123+35
FWD 7



L


CELL 4
300 - 350 ft

1123+35

TWO

1123+85

50'



PROBABLY a tear from vehicle?
looks like R-L


CELL 4
350 - 400 ft

1123+65

Two
8

1124+35

Two
9




CELL 4
400 - 450 ft

1124+35

Two 6

Two 10
1124+85

0 - RAV



9

CELL 4
450 - 500 ft


1125+00

1124+85

FWD
10

1125+35

Vehicle scrapes?



10