

9/24/13 BAT

(Previous Survey 10/2/12)

File ML06

Cell 605 | Cell 305

5/7/2014 Spring 2015
Mike Q

DAV

CELLS 305-405
300 - 350 ft

unsealed joints

PANEL 2


1128+80

JT 4020

JT 4021

JT 4022

1128+30



10/24/2014 DAV
8-20-2015 BJB

CELL 305
350 - 400 ft

PANEL 3

PANEL 5

1129+30

JT 4023

10'

20'

JT 4024


30'

JT 4025

40'

1129+80

50'



Cell 305/Cell 405


1130+30

NEW BIT PATCH
4'X7'
JT 4029

PANEL 9

8 PANE 8

PANEL 7



Subtract cracks in Patch
include cracks drawn
out of the patch area

over 10/27/2011

FWD
PAGE 32


Instrumentation - crack from conduit

JT 4031

JT 4030

JT 4031

JT 4032



CELL 405
500 - 550 ft

PANEL 33

1130+80

JT 4033


FWD 34

JT 4034

PANEL 35

JT 4035

1131+30



FWD 34

75

CELL 405
550 - 600 ft

Cell 405 Transition to 306

PANEL
37

NEW PATCH JUNE 2015
5' x 3' 155g. ft.
BIT.

JT 4036

JT 4037

