

1d

1132+60.8

CELL 306
50-100 Feet

P-6

P-5

P-4


1132+10.8


Joint-4272

Joint-4273

Joint-4274

Joint-4275





1133 + 60.8

P-13

FWD
(3)

Joint-4281

CELL 306
150 - 200 Feet

P-12


Joint-4280

P-11

Joint-4279

P-10

1133 + 10.8



1134+10.8

Joint 4285

1134+00

P-15

Joint 4284

CELL 306
200-250 Feet


P-15

Joint 4283

P-14

Joint 4282

1133+60.8



1134 + 60.8

P-2

Joint 4283

P-1

Joint 4287

CELLS 306-406
250 - 300 Feet

P-0


Begin Cell 406 1134 + 22.4

End Cell 306 1134 +

Joint 4286

P-17

1134 + 10.8



FWD
P. 2

Cell 306 ← → Cell 406

1/2

1135+60.8

Joint-4295

P-8

Joint-4294

CELL 406
350 - 400 Feet


P-7

Joint-4293

P-6

Joint-4292

1135+10.8



9.0

1136+10.8

P-12

Joint-4298

1136+00

P-11

CELL 406
400 - 450 Feet

Joint-4237


P-10

Joint-4296

3 T cracks

P-9

1135+60.8



3" sp

h

1136+60.8

P-15

Joint-4301

CELL 406
450 - 500 Feet

P-14


Joint-4300

P-13

Joint-4299

P-12

1136+10.8



P 13

12

1137+10.8

Joint 4305

P-18

1137+00

Joint 4304

CELL 406
500 - 550 Feet


P-17

Joint 4303

P-16

Joint 4302

1136+60.8



46

CELL 406
550 - 600 Feet
Begin Cell 7 1137 + 14
End Cell 406 1137 + 14

Joint 4306

1137 + 10.8