

11/14/18 MCV Will report loss of surface binder in inside lane
3/26/19 MCV No Change

Cell 186
0-50, pp 1 of 4

Begin Station 166+19.1

Station 166+69.1

Inside Lane

Outside Lane

Ravel Low Sew

Cell 186

50 - 100, pp 2 of 4

Station 166+69.1

Station 167+19.1

Inside Lane

Outside Lane

Ravel low sev

Cell 186

100 - 150, pp 3 of 4

Station 167+19.1

Station 167+69.1

Inside Lane

Outside Lane

Road for Sew

Cell 186

150 - 201, pp 4 of 4

Station 167+69.1

End Station 168+20.2

Inside Lane

Outside Lane

R

R

Koller -
Ravel