


5/1/18 RST
3/18/19 MW

18x2.71

Sub-cell 238
Gravel Shoulder

Sub-cell 139




Gravel Shoulder

1/6 1/15

Sub-cell 139


Gravel Shoulder



Gravel Shoulder

2/6 2/12

Sub-cell 139




DP - Divided Panels

3/6

3/10

Sub-cell 139



Inside lane outer panels replaced at 4" tick on 9/27/2019. Different fiber used


Gravel Shoulder

4/6 4/10


$$\frac{5}{6} \quad \frac{5}{10}$$

Sub-cell 139

Sub-cell 239




Gravel Shoulder

6/6
239
1/6

2/7/10 ML


Sub-cell 239



Gravel Shoulder

2/6/10

Sub-cell 139




Gravel Shoulder

3/6 8/11

Sub-cell 239

Sta. 100+73	J-2864	P-63	→
+83	J-2865	P-64	
+88.8	J-2866	P-65	
+94.1	J-2867	P-66	
+100.4	J-2868	P-67	
+106.4	J-2869	P-68	
+12.4	J-2870	P-70	
+18.4	J-2871	P-71	
+24.4	J-2872	Sta. 101+23	→




Not
access
entire
d/s

Gravel Shoulder


4/6 8/12

Sub-cell 239



5/6 10/12

Sub-cell 239



P-80

Gravel Shoulder

6/6 10/17