



INTERNATIONAL ROAD DYNAMICS INC.

13133 W Cambridge Ave. Goodyear, AZ 85395

Phone (623) 256-9900 Fax: (623) 536-1513

- Site Service Report -

IRD SO#: 11013C

From: Greg Felsing

Project Name: AZ LTTP-2

Project Location: I-10 @ MP 108.5 EB

Service Date(s): Jan.27,2009

Weather: sunny 60F

IRD Ref:

To: Cindy Mantie

Job Description: Periodic maintenance,

Work Completed: Checked all sensors and loops, batteries, solar cell, regulator, modem.

Work Remaining: Repair broken piece of epoxy, BP2 homerun

Parts Used: none

Mileage / Travel Time: 42miles/1hrs

Time Spent on Site: 1 hour

Notes: Epoxy is cracking, and in one place broken out of BP2 home run

Action Items:

Item	Action Required	Ownership
1.	Fix epoxy	IRD