



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: June 5, 2009

IRD Sales Order: 10113-R

To: Ray Pollon

From: Shawn Brown, Bruce Myers, Cindy Matie

Project Name/Location: Louisiana, LTPP (LA), US171 NB MP7.9, Calcasieu Parish

Service Date(s): November 27th, 2008

Weather: Cloudy/Cool, 55F Temp

Job Description:

- Performed routine site maintenance

Work Completed:

- Fixed temperature sensor to pullbox lid to obtain better temperature readings
- Measure sensor electrical characteristics
- Verify system operation
- Noted Low Voltage Disconnect to display "HVD" (High Voltage Disconnect)

Work Remaining:

- Will need to check further as to cause of HVD being displayed on Star-controller. May indicate possible problem with battery and/or controller. Will be travelling through area next week and will investigate further at that point.

Schedule Include Estimate to Complete (on-track, ahead, behind):

- On-track

Parts Used:

- None



TM
INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM
INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com





TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com






TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com






TM INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com






INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com



Pre-mature Equipment Failure:

- None

Mileage / Travel Time:

- As required

Safety Concerns:

- None noted

Issues Related to Sub-Contractors:

- None

Other Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		