

**From:** Trevor Ritchie  
**Sent:** Wednesday, September 07, 2011 8:25 AM  
**To:** Cindy Ireland  
**Subject:** Maine Itpp

Hello,

So I am here in Maine, went to the site and found that they milled and repaved the road. So all the in road sensors are gone except for the temperature sensor.

I disconnected the loops and the Kistlers from the Isinc so they would not cause any problems. I took a picture of the road and attached it to the Jira ticket as well as updated what I found. I believe the last data file was Aug.22/11.

**Trevor Ritchie**  
**Field Services Supervisor / Northeast Regional Supervisor**  
IRD (International Road Dynamics, Inc.)

Phone: (518) 265-7658  
Fax: (208) 730-3031  
Website: [www.irdinc.com](http://www.irdinc.com)  
*IRD is Customer Driven!*

---

This E-mail message (including attachments, if any) is intended for the use of the individual or entity to which it is addressed and may contain information that is privileged, proprietary, confidential and exempt from disclosure. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender and erase this E-mail message immediately.