



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: June 9, 2009

IRD Sales Order: 11013

To: Cindy Mantie

From: Jonathan Glynn

Project Name/Location: LTTP site / Rt 15 mp 4.7, MD

Service Date(s): 5-5-09

Job Description: Perform routine maintenance

Work Completed:

- Visually inspected site and took pictures (see attached). Rubber on bending plates is scrapped a bit.
- Connected to ISINC and watch traffic for a while to verify proper operation.
- Performed tests. See below.

Work Remaining:

Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used:

Pre-mature Equipment Failure:

Mileage / Travel Time:

400 miles / 6 hrs

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:

Bending plates:

Upstream right:

Exc: 978ohms

Sig: 843ohms

Downstream left:

Exc: 976ohms

Sig: 842ohms



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

Loops:

Upstream: 0.54ohms Meg: 0.227Mohms

Downstream: 0.50ohms Meg:

Line AC: 123V

DC: 13.5V

Battery: 13.53V

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		