



INTERNATIONAL ROAD DYNAMICS INC.
 702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9
 Phone (306) 653-6600 Fax: (306) 242-5599

- Site Service Report -

June 9, 2009

IRD SO#: **IRD Ref:**
From: Jorge Rubio **To:** Shawn Brown, Bruce Myers
Project Name: Bemidji LTTP (MN)
Project Location: I-2 Mile Post 91.5
Service Date(s): May 22, 2008
Weather: Cloudy 68F

Job Description: Site inspection and maintenance.

Work Completed:

- Loops, kistlers, piezos and cabinet visually inspected (good condition)
- iSINC components working as expected.
- Powered down iSINC to remove each card and cleaned slots and connectors.
- Each ferule connector removed to check each one of the sensors. (see report for each one of the sensors)
- Installed new ferule connectors.
- Powered back on the iSINC and observed LED activity (working right)
- Connected laptop and observed traffic activity (working right)
- Vehicle records displayed as expected.
- Left iSINC running as expected.

Work Remaining: None

Parts Used: 16 UC Ferrule 20AWG 1.1 X 8mm Wht PN 460029

Mileage / Travel Time: 570 MI – 9 HRS

Time Spent on Site: 3 hours

Notes: FTTP site, components and pavement in good condition.

Action Items:

Item	Action Required	Ownership
1.		