



INTERNATIONAL ROAD DYNAMICS INC.
 702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9
 Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: June 8, 2009

IRD Sales Order: 11013

To: Cindy Manti

From: Steven Schroeder

Project Name/Location: PA LTTP Milesburg, Pa

Service Date(s): 1-14-09

Job Description: Replace WCU II.

Work Completed: Arrived on site at 11:00am. Replaced WCU II. Had Jeff Robertson Dial in and verify proper operation. Left site at 12:30pm

Work Remaining: no work remaining

Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used:

- 1- WCU II Card
- Old Card S/n 061004401
- New Card S/n 680913530

Pre-mature Equipment Failure:

WCU II card failed prematurely- Sent to IRD for testing.

Mileage / Travel Time:

368 miles/ 5 hours travel

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:

Action Items:

| Item | Action Required | Ownership |
|------|-----------------|-----------|
| 1. | | |
| 2. | | |
| 3. | | |
| 4. | | |