



17 not raised
cracks distinctly
lots of fatigue in RC
little in LL



CELL 17


ML10-F-17

DISTRESS SURVEY – APRIL 24-30, 2001




CELL 17
K1110-E-17

DISTRESS SURVEY – APRIL 24-30, 2001




DISTRESS SURVEY – APRIL 24-30, 2001




CELL 17

MI 10-F-17


DISTRESS SURVEY – APRIL 24-30, 2001



DISTRESS SURVEY – APRIL 24-30, 2001




DISTRESS SURVEY – APRIL 24-30, 2001



CELL 17


MI 10-F-17

DISTRESS SURVEY – APRIL 24-30, 2001



CELL 17
ML10-F-17

DISTRESS SURVEY – APRIL 24-30, 2001



CELL 17

DISTRESS SURVEY - APRIL 24-30, 2001