

18

lots of
fatigue
seals are
in good
shape

1216+85


1216+35



CELL 18

MI 10-F-18


DISTRESS SURVEY - APRIL 24-30, 2001




CELL 18

.ML10-F-18

DISTRESS SURVEY – APRIL 24-30, 2001




DISTRESS SURVEY – APRIL 24-30, 2001




CELL 18

DISTRESS SURVEY – APRIL 24-30, 2001




DISTRESS SURVEY – APRIL 24-30, 2001




CELL 18

1110.E-18

DISTRESS SURVEY – APRIL 24-30, 2001




DISTRESS SURVEY – APRIL 24-30, 2001



CELL 18

ML10-F-18

DISTRESS SURVEY – APRIL 24-30, 2001



CELL 18

MI 10-F-18

DISTRESS SURVEY - APRIL 24-30, 2001