


4/14/2005
BSW

0-50 ft

$$T_{Dnk} = 100 \text{ ft}$$
$$6H = 2124 \text{ ft}$$

1113+19.5

**DISTRESS SURVEY**
12/29/04

$T_{DL} = 40 \text{ ft} \checkmark$
 $G_H = 2124 \text{ ft}$
 $P_{DL} = 50 \text{ ft}$


1113+19.5

CELL-2

50-100 ft

TD_L = 58 ft
 TD_M = 42 ft
 GH = 3136 ft

1112+69.5



DISTRESS SURVEY
 12/29/04

TD_L = 28 ft
 GH = 3136 ft
 PFL = 50 ft

CELL-2


100-150 ft

$$TD_L = 86 \text{ ft}$$

$$TD_M = 10 \text{ ft}$$

$$GH = 112 \text{ ft}$$

1112+69.5



DISTRESS SURVEY

12/29/04

$$TD_L = 14 \text{ ft}$$

$$GH = 112 \text{ ft}$$


$$PJ \ 4L = 44 \text{ ft}$$

CELL-2

150-200 ft

TDL = 48 ft
TDM = 36 ft
GH = 112 ft

1111+69.5




DISTRESS SURVEY
12/29/04

TDL = 4 ft + v
GH = 112 ft
PSL = 50 ft

200-250 ft

$$\begin{aligned} TD_L &= 100 \text{ ft} \\ GL &= 2124 \text{ ft} \\ GL &= 2 \text{ ft} \end{aligned}$$

1111+19.5


**DISTRESS SURVEY**
12/29/04

$TDL = 12 \text{ ft} \checkmark$ $PJ-L = 50$
 $PATCH = 36 \text{ ft}$
 $GH = 2124 \text{ ft}$

CELL-2

250-300 ft

check FWD points
 $TD_L = 76ft$
 $TD_M = 8ft$
 $GM = 18ft$
 $GM = 3 / 30ft$
 $1110+69.5$



DISTRESS SURVEY


12/29/04

$GH = 2 / 24ft$
 $DJL = 50ft$
 $GL = 1ft$

CELL-2

300-350 ft

$TD_L = 100 \text{ ft}$
 $6M = 1/12 \text{ ft}$
 $6L = 1/2 \text{ ft}$



DISTRESS SURVEY
12/29/04

$TD_L = 42 \text{ ft}$
 $6H = 1/12 \text{ ft}$
 $JP = 50 \text{ ft}$


CELL-2

350-400 ft

$$TD_L = 88 \text{ ft}$$

$$GM = 2/24 \text{ ft}$$

1109+69.5



DISTRESS SURVEY

12/29/04

$$TD_L = 80 \text{ ft}$$


$$GH = 1/12 \text{ ft}$$

$$GM = 1/12 \text{ ft}$$

$$PDL = 50 \text{ ft}$$


SENSOR AREA

TDL-100ft
GM=318ft
36

**DISTRESS SURVEY**
12/29/04

$TD_L = 32 \text{ ft}$
 $JPL = 2 \text{ ft}$
 $GM = 31 \text{ ft}$
 36

TP_L = 78 ft
GM = 2124 ft 69.5

**DISTRESS SURVEY**
12/29/04

TP_L = 50 ft + ✓

6H = 1 \ 12 ft

6M = 1 \ 12 ft

6L = 1 \ 9 ft