

CELL-29

0-50 ft

$$G_L = 1/12$$

~~Edge L = 50~~

$$4bL = 77$$


$$F_M = 12$$

~~F = 12~~

$$4bM = 10$$

191+20

191+70



DISTRESS SURVEY

12/29/04

5/19/05
TRC

$$G_H = 1/12$$

~~F = 12~~

$$4bL = 71$$


CELL-29
50-100 ft

$6L = 3/6'$

~~Fig 10~~

$4aL = 5$

$4bL = 11$



$CL_L = 31$

$6L = 1/6$

$4bL = 19$



DISTRESS SURVEY
12/29/04


CELL-29

100-150 ft

$$6L = 1/12$$

$$4aL = 5$$

$$4bL = 38 \quad 4bM = 12$$



DISTRESS SURVEY

12/29/04

$$CLL = 27$$

$$6M = 1/12 \quad 2/21$$

$$4bL = 14 \quad 4aL = 21$$

CELL-29


150-200 ft

$$GL = 1/3$$

$$4aL = 15$$

$$4bL = 56$$

$$4bM = 10$$



DISTRESS SURVEY
12/29/04

$$CLL = 58$$

$$4aL = 19$$

$$4bL = 19$$

$$GL = 2/11$$


CELL-29

200-250 ft

$$6L = 1/12$$

$$4aL = 5$$

$$4bL = 50$$



DISTRESS SURVEY
12/29/04

$$6L = 5/11$$

$$6M = 9/36$$

$$4aL = 6$$

$$4aM = 12$$


$$4aH = 70$$



CELL-29

250-300 ft

4aL = 35
6L = 3/26
4bM = 113



DISTRESS SURVEY
12/29/04

CLL = 50
6L = 5/38 6M = 1/12
4aL = 13 Patch H = 13
4bL = 4

300-350 ft

$$4bL = 21$$


350-400 ft

$$4aH = 11$$

188+20

187+70

350'


360'

370°

380'

390'

400'


**DISTRESS SURVEY**
12/29/04
$$CL_L = 31$$
$$G_L = G/15$$
$$46L = 1$$

Fatigue L = 48

CELL-29

400-450 ft

$GM = 5/49$ $4aL = 14$
 $6L = 3/10$
 Patch H = 379



DISTRESS SURVEY
 12/29/04

$CLL = 34$
 $6H = 2/24$
 $4bL = 4$
 $4aL = 10$

$F_M = 10$
 $F_H = 8$




$$6L = 13/74$$

CELL-29

$$F_H = 194$$

450-500 ft

**DISTRESS SURVEY**
12/29/04
$$CL_L = 50$$
$$4b_L = 7$$
