

1125+35


~~4/14/2005~~
~~1351~~

CELL-4

0-50 ft

$TD_L = 100 \pm \checkmark$
50

1224+85



DISTRESS SURVEY


12/29/04 10/17/05 TRC

$TD_L = 100 \pm \checkmark$
 $GL = 114 \pm$
 $JPM = 20 \pm$
 $JPI = 4 \pm$

CELL-4

50-100 ft

TD_L = 78 ft
 GH = ~~30~~ 21 18 ft
 GM = 11 12 ft




DISTRESS SURVEY
 12/29/04

TD_L = 100 ft ✓
 GH = 21 24 ft
 GM = 11 12 ft
 TD_I = 27 ft

100-150 ft

$$6M = 1 \sqrt{124}$$

1123+85

**DISTRESS SURVEY**
12/29/04


64-11244

$P_{5L} = 44 \text{ ft}$

CELL-4

150-200 ft

TDL = 50 ft
TDM = 50 ft
GM = 2 | 22 ft
GL = 1 | 6 ft




DISTRESS SURVEY
12/29/04

TDL = 80 ft
TDM = 19 ft
GM = 3 | 28 ft
GH = 2 | 24 ft

200-250 ft

$$6M = 12 ft$$

1122+85

**DISTRESS SURVEY**
12/29/04


$TD_L = 90 \text{ ft}$
 $6H = 112 \text{ ft}$
 $6M = 112 \text{ ft}$

SENSOR AREA

CELL-4

250-300 ft

TDL = 100 ft
GH = 112 ft



DISTRESS SURVEY
12/29/04

TDL = 100 ft
GH = 112 ft
GM = 2112 ft

SENSOR AREA

CELL-4


300-350 ft

$$TD_L = 100 \text{ ft}$$

$$GH = 1119 \text{ ft}$$

1121+85

1122+35



DISTRESS SURVEY

12/29/04

$$TD_L = 100 \text{ ft}$$

$$GH = 2115 \text{ ft}$$

$$GL = 215 \text{ ft}$$


$$PJL = 36 \text{ ft}$$

SENSOR AREA

1121+39.5

350-400 ft

$$1121 + 62.504 = 1121 + 57.96$$

$$P.T. = P.O.T$$
**DISTRESS SURVEY**
12/29/04

61 $TD_L = 400 \text{ ft}$
 $61 = 3 \mid 26 \text{ ft}$
 $PJL = 50 \text{ ft}$

1121+39.5

CELL-4


400-450 ft

TDL = 90 ft

GH = 112 ft

GL = 112 ft

1120+89.5



TDL = 100 ft

GH = 2124 ft

GL = 115 ft

PJL = 22 ft


CELL-4

450-500 ft

TDL = 94 ft
GH = 2124 ft

1120+89.5

1120+39.5



DISTRESS SURVEY
12/29/04

TDL = 100 ft
GH = 1112 ft
GM = 4126 ft