


4/19/2008

0-50 ft

$$6M = 2/24$$

1216+35



$TD_L = 86 \text{ ft}$
 $6L = 1112 \text{ ft}$
 $6M = 2124 \text{ ft} \quad 5/60 \checkmark$
 $CL_{\text{TH}} = 50 \text{ ft}$

DISTRESS SURVEY 4/17/06
~~12/29/04~~ 10/17/05 TRC

2 patches
under stern


$$T O_m = 9'$$

CELL-18

50-100 ft

$L = 207'$
 $GM = 112'$
 $GH = 112'$

1215+85



DISTRESS SURVEY
12/29/04


$TD_L = 79'$
 $GL = 118'$
 $GM = 2123'$
 $GH = 112'$
 $CL = 50'$

CELL-18

100-150 ft

TD_L = 72 ft
 GL = 114 ft
 GM = 112 ft
 GH = 112 ft

1215+35




DISTRESS SURVEY
 12/29/04

TD_L = 58 ft
 GL = 110 ft
 GH = 224 ft
 4M = 50 ft

CELL-18

150-200 ft

TDL = 64 ft
TDM = 34 ft
GM = 1/12 ft
GH = 1/12 ft



DISTRESS SURVEY

12/29/04


TDL = 26 ft
GM = 3/26 ft
GH = 2/24 ft
4M = 50 ft

CELL-18

200-250 ft

TD_L = 58 ft
TD_M = 40 ft
GH = 41.52 ft

1214+35




DISTRESS SURVEY
12/29/04

CELL-18

250-300 ft

$TD_L = 50 \text{ ft}$
 $TD_M = 50 \text{ ft}$
 $6L = 214 \text{ ft}$
 $6M = 112 \text{ ft}$
 $6H = 112 \text{ ft}$

1213+85



DISTRESS SURVEY
12/29/04

$TD_L = 68 \text{ ft}$
 $6L = 116 \text{ ft}$
 $6H = 3136 \text{ ft}$
 $TD_M = 50 \text{ ft}$

300-350 ft

GM = 3136 ft

1213+35

350'

12'

8'

4'

 ϕ

-4'

8'

-12'

350'

12/29/04

$$4M = 50 \text{ ft}$$


CELL-18

350-400 ft

TD_L = 50 ft +
 TDM = 50 ft +
 6L = 4129 ft +
 6M = 1113 ft +
 6H = 1112 ft +

1212+85

1213+35



DISTRESS SURVEY
 12/29/04

TD_L = 79 ft +
 6M = 4147 ft +
 4M = 50 ft +

CELL-18

400-450 ft


$TD_L = 39 \text{ ft}$

$TD_M = 58 \text{ ft}$

$GM = 2124 \text{ ft}$

1212+85

1212+35



DISTRESS SURVEY

12/29/04

$TD_L = 74$

$GM = 2124 \text{ ft}$


$4M = 50 \text{ ft}$

CELL-18

450-500 ft

TDL = 35 ft
TDM = 64 ft
GM = 4140 ft

1211+85



DISTRESS SURVEY
12/29/04

TDL = 62 ft
GM = 112 ft
GH = 112 ft