

no distress
need paint stripes

CELL-28

0

185+50

0-50 ft

0' 10' 20' 30' 40' 50'

12' 12'

102k 8'

8'

4'

4'

0'

0'

-4'

-4'


-8'

-8'

-12'

-12'

0' 10' 20' 30' 40' 50'



111

DISTRESS SURVEY

12/29/04

05-119-05

the same

10/36/06

10/19/05

no


$F_m = 14$

✓

Patch L = 160

CELL-28

50-100 ft




DISTRESS SURVEY
12/29/04

$F_m = 16$

Patch L = 27



CELL-28




CELL-28

$$F_L = 10$$

$$F_M = 22$$

$$4bL = 12$$

150-200 ft




DISTRESS SURVEY
12/29/04



CELL-28

200-250 ft



DISTRESS SURVEY

12/29/04,

05/19/05


46L=17

F-H=14



CELL-28

$F_H = 18$




DISTRESS SURVEY
12/29/04

$F_L = 2$



CELL-28

300-350 ft




DISTRESS SURVEY
12/29/04

CELL-28

$F_H = 12$

350-400 ft



DISTRESS SURVEY

12/29/04

06/19/05


$F_L = 2$



CELL-28

0


400-450 ft



DISTRESS SURVEY
12/29/04

CELL-28

$F_M = 8$



DISTRESS SURVEY
12/29/04

$F_L = 4$

