


$$4aL = 3$$

CELL 35
50-100 ft

$$GL = 9/46$$

$$4aL = 3$$

$$CL_L = 50$$



$$GL = 9/49$$


DISTRESS SURVEY
12/29/04

CELL 35

100-150 ft

$$GL = 11/63$$

$$CL = 50$$



$$GL = 17/77$$

$$4aL = 3$$

DISTRESS SURVEY
12/29/04



CELL 35

150-200 ft

6L = ~~10/34~~ 9/38


6L = 1-1/13
CLL = 50

4aL = 9

4aM = 23

4bL = 7

77+87



6L = 22/76

4aL = 17

DISTRESS SURVEY

12/29/04




CELL 35

200-250 ft

$$6L = 10/39$$

$$4aL = 24$$

$$CLL = 50$$



$$6L = 12/44$$

$$4aL = 24$$

DISTRESS SURVEY
12/29/04




CELL 35

250-300 ft

$$6L = 17/56$$

$$4aL = 28$$

$$CLL = 80$$



DISTRESS SURVEY
12/29/04

$$6L = 20/88$$

$$4aL = 15$$

←→
SENSOR AREA

✓


CELL 35

300-350 ft

$$6L = 12/50$$

$$4aL = 82$$

$$CL_L = 50$$



DISTRESS SURVEY
12/29/04

$$6L = 10/53$$

$$4aL = 42$$

$$4bL = 3$$

CELL 35

350-400 ft

$$6L = 6/15$$


$$6M = 3/33$$

$$CL_L = 50$$

$$4aL = 75$$

$$4aM = 8$$

* yikes



$$6L = 18/60$$

$$4aL = 3$$

DISTRESS SURVEY


12/29/04



CELL 35
400-450 ft

GL = 8/41
GM = 1/10
4aL = 48
4aM = 55

FM = 14
CLL = 50



GL = 9/50
4aL = 15

DISTRESS SURVEY
12/29/04



CELL 35


450-500 ft

$$F_m = 30 \text{ } 56$$

$$F_L = 36$$

$$G_L = 5/18$$

$$CL_L = 42$$



DISTRESS SURVEY
12/29/04

$$G_L = 4/23$$