

1125+35

~~4/11/05~~
350


CELL-4

0-50 ft

50

1224+85

✓



DISTRESS SURVEY 4/11/05
-12/29/04 10/17/05 TRC 10/23/06


$TD_L = 100 \pm$
 $GL = 114 \pm$
 $JPM = 20 \pm$
 $TDI = 4 \pm$

CELL-4

50-100 ft

1 L2 = 18 ft
 6H = ~~30~~ 21 ft
 6M = 112 ft

1124+35




DISTRESS SURVEY
 12/29/04

TDL = 100 ft ✓
 6H = 2124 ft
 6M = 1112 ft
 TDI 07-12

100-150 ft

$$6M = 1 \mid 124 +$$

1123+85

DISTRESS SURVEY
12/29/04
$$TDL = 50 \text{ ft}$$

TDM = 15 ft

64-11288

$$P_{5L} = 44 \text{ ft}$$

SENSOR AREA


CELL-4

150-200 ft

TD_L = 50 ft
TD_M = 50 ft
GM = 2 | 22 ft
GL = 1 | 6 ft

1123+85

1123+35



DISTRESS SURVEY
12/29/04


TD_L = 80 ft
TD_M = 19 ft
GM = 3 | 28 ft
GH = 2 | 24 ft

CELL-4

200-250 ft

$$\begin{aligned} TD_L &= 30\text{ft} + 5\text{ft} \\ TD_M &= 25\text{ft} + 26 \\ GM &= 12\text{ft} \end{aligned}$$

1122+85



DISTRESS SURVEY
12/29/04

$$\begin{aligned} TD_L &= 90\text{ft} \\ GM &= 12\text{ft} \\ GM &= 12\text{ft} \end{aligned}$$

CELL-4


250-300 ft

$$TDL = 100 \text{ ft}$$

$$GH = 1/12 \text{ ft}$$

1122+85

1122+35



DISTRESS SURVEY
12/29/04

$$TDL = 100 \text{ ft}$$

$$GH = 1/12 \text{ ft}$$

$$GMA = 2/12 \text{ ft}$$


←→
SENSOR AREA

300-350 ft

$$TD_L = 100 \text{ ft} + 64 = 164 \text{ ft}$$

1122+35

1121+85

DISTRESS SURVEY
12/29/04


$TD_L = 100 \text{ ft}$
 $6H = 215 \text{ ft}$
 $6L = 215 \text{ ft}$
 $PJL = 36 \text{ ft}$

SENSOR AREA

1121+39.5

350-400 ft

1121+85




$TD_L = 400 \text{ ft}$
 $6H = 3 \mid 26 \text{ ft}$
 $PJL = 50 \text{ ft}$

CELL-4

400-450 ft

TDL = 90 ft
 GH = 1142 ft
 GM = 1142 ft



HOLE
 SURVEY
 mission


DISTRESS SURVEY
 12/29/04

TDL = 100 ft
 GH = 2124 ft
 GL = 115 ft
 PJL = 22 ft

1120+39.5

450-500 ft

1120+89.5

DISTRESS SURVEY
12/29/04

TDL = 100 ft
GH = 1112 ft
GM = 4126 ft