


2nd/10/15

## 0-50 ft

$$6t = 1/4 \neq t$$
$$GM = 116 \text{ ft}$$

1227+55



10/25/06  
~~4/17/06~~

12/29/04

каждый трс

4/10/07  
E. Johnson

$$TDL = 44 \text{ ft}$$
$$6M = 3/2 \text{ } \& \text{ } \neq +$$


PJM = 18¢

1 D<sub>L</sub> = 68 ft

# CELL-20 50-100 ft

1227+55

1227+05



DISTRESS SURVEY  
12/29/04

TD<sub>L</sub> = 14  
6L = 1110 ft  
6M = 1112 ft ✓






# CELL-20

150-200 ft

DL = 16ft

GM = 2\18ft



DISTRESS SURVEY  
12/29/04

GL = 1\2ft  
GM = 1\12ft

←→  
SENSOR AREA

✓


PD

# CELL-20

200-250 ft

1226+05

1225+55



DISTRESS SURVEY  
12/29/04

JPL = 13 ft +  
GL = 2 \ 15 ft +

✓

# CELL-20

250-300 ft


$$TDL = 21\# +$$

$$GM = 1/12\# +$$

$$GL = 1/3\# +$$

1225+55

1225+05





# CELL-20

300-350 ft


$$TDL = 15 \text{ ft}$$

$$GL = 2 \text{ } 16 \text{ ft}$$

$$GM = 1 \text{ } 11 \text{ ft}$$

$$4L = 1 \text{ } 2 \text{ ft}$$

1224+55



DISTRESS SURVEY  
12/29/04

$$GL = 2 \text{ } 12 \text{ ft}$$


$$GM = 1 \text{ } 12 \text{ ft}$$

350-400 ft

$6L = 2 \mid 16ft$   
 $6M = 2 \mid 14ft$   
 $4L = 2 \mid 11ft$

1224+55

1224+05

**DISTRESS SURVEY**  
**12/29/04**
$$\begin{aligned} TDL &= 8 \mid 46 \neq + \\ GL &= 6 \mid 24 \neq + \\ GM &= 11 \mid 12 \neq + \end{aligned} \quad \checkmark$$




# CELL-20

400-450 ft

~~728~~  
6L = 115 ft  
4L = 113 ft

1223+55



DISTRESS SURVEY  
12/29/04

TDL = 5 \ 34 ft  
6L = 3 \ 18 ft  
JPL = 4 ft  
TDM = 38 ft


# CELL-20

450-500 ft

$$4L = 110 \text{ ft}$$

1223+55

1223+05



DISTRESS SURVEY  
12/29/04

SLURRY  
LOSS  
HOLE  
3/4" Deep

$$\begin{aligned} TDL &= 8 \text{ ft} \\ 6L &= 1 \setminus 8 \text{ ft} \\ JPL &= 20 \text{ ft} \end{aligned}$$